

Team Penalty

From: FSPT Team

Date: 07/09/2024

To: Ü Motorsport - 296

Time: 23:00

Infringed rule(s)

T2.1.1	<i>The vehicle must be designed and fabricated in accordance with good engineering practices.</i>
--------	---

Team's action

A loose bolt was found inside the cockpit. It was determined to be one of the "bullhorn's" mounting bolts.

Penalty applied

IN12.1.4 Group B violation of the rules with advantage for the team (e.g. aerodynamics). A penalty of 0.6 seconds shall be applied for the skidpad event. The penalty applies to both runs of the 2nd driver.

Responsible

António Bento
Chief Scrutineer

Protest deadline: 11:59 08/09/2024