

Team Penalty

From: FSPT Team

Date: 07/09/2024

To: Team Bath Racing Electric - 67

Time: 23:00

Infringed rule(s)

IN12.1.5	<i>Violation of the rules concerning safety or the environment (e.g. BOTS, safety harness issues, ground clearance, fluid leaks other than plain water, noise) results in DQ since entering the dynamic area.</i>
-----------------	---

Team's action

After post-inspection for both of the first driver's runs, a brake fluid leakage was found around the brake fluid reservoirs. The team was given an opportunity to correct this in time for the second driver's runs. The issue persisted for the second driver's runs.

Penalty applied

Disqualification for all runs.

Responsible

António Bento
Chief Scrutineer

Protest deadline: 11:59 08/09/2024